

DRAFT

**AUGUST 2012
QUARTERLY GROUNDWATER MONITORING REPORT
VULCAN-LOUISVILLE SMELTING SITE
NORTH CHICAGO, LAKE COUNTY, ILLINOIS**

December 5, 2012

Prepared for:

U.S. Environmental Protection Agency
77 West Jackson Boulevard
Chicago, IL 60604



100 W. Monroe Street, Suite 300, Chicago, IL 60603

TABLE OF CONTENTS

1.0	INTRODUCTION	3
2.0	SITE DESCRIPTION AND BACKGROUND	4
3.0	SITE PREPARATION.....	7
4.0	MONITORING WELL SAMPLING.....	8
4.1	Water Level Measurements.....	8
4.2	Groundwater Sampling	8
4.2.1	Purging and Sampling of Monitoring Wells.....	8
4.2.2	Sample Collection Order Used	9
4.2.3	Sample Analysis.....	9
4.2.4	Disposal of Purged Water	10
5.0	ANALYTICAL RESULTS & CONCLUSIONS	11

LIST OF FIGURES

Figure 1 Groundwater Monitoring Well Network Map

LIST OF TABLES

Table 4-1 Groundwater Parameter Stabilization Criteria
Table 5-1 Sample Analytical Results
Table 5-2 Water Quality Measurements

LIST OF APPENDICES

Appendix A Validated Analytical Data Package



LIST OF ACRONYMS AND ABBREVIATIONS

DCE	Dichloroethene
EE/CA	Engineering Evaluation/ Cost Analysis
HASP	Health and Safety Plan
NA	Natural Attenuation
QAPP	Quality Assurance Project Plan
QA/QC	Quality Assurance/Quality Control
START	Superfund Technical Assessment and Response Team
OTIE	Oneida Total Integrated Enterprises
PCBs	Polychlorinated Biphenyls
TCE	Trichloroethylene
TDD	Technical Direction Document
TOC	Total Organic Carbon
U.S. EPA	U.S. Environmental Protection Agency
VC	Vinyl Chloride
VOCs	Volatile Organic Compounds

